



Dependable Products From People You Trust

# OFI TESTING EQUIPMENT, INC.

11302 Steeplecrest Drive, Houston, Texas 77065 Phone (832) 320-7300 Fax (713) 880-9886 Web www.ofite.com


## CALIBRATION CERTIFICATE

Temperatures are calibrated to meet or exceed the requirements stated in API RP 13B-1 and API RP 13B-2

AS FOUND CHART

AS LEFT CHART

| LAB TEMPERATURE | LAB HUMIDITY | PART NUMBER | SERIAL NUMBER | SET POINT | RESULT   | ALLOWABLE RANGE | CALIBRATION DATE | DUE DATE  | TECHNICIAN |
|-----------------|--------------|-------------|---------------|-----------|----------|-----------------|------------------|-----------|------------|
| 74.00 °F        | 45.00 %      | 165-14-3    | 5384890000007 | 930.0 °F  | 908.3 °F | 860-1000 °F     | 3/12/2025        | 3/12/2026 | SM         |



Calibration station has been calibrated using instruments which are traceable to NIST.

|   |   |   |
|---|---|---|
| <b>CAL STATION SERIAL NUMBER:</b> 6B-11 | <b>CAL STATION CALIBRATION DATE:</b> 11/11/2024                               | <b>CAL STATION DUE DATE:</b> 11/11/2025   |
| <b>AMBIENT MONITOR MODEL:</b> RH300     | <b>AMBIENT MONITOR S/N:</b> Z395285   | <b>AMBIENT MONITOR CAL DATE:</b> 08/20/2024 <b>AMBIENT MONITOR DUE DATE:</b> 08/20/2025 |
| <b>UNCERTAINTY:</b> ± 2.8°C / 5°F       | <b>CALIBRATION PROCEDURE USED:</b> Retort Calibration Procedures API RP 13B-1 |   |

- Channel 2
- Plot 1
- Plot 2
- Plot 3
- Plot 4

AS FOUND CONDITION:

CALIBRATION RESULT: Accepted